

OCS-10A

CRANE SCALE



Bluetooth	Enabled
Function	Zero, tare , hold, auto power off battery supervision, overload alarm, unit switch, auto calibration
Display	20mm LCD backlight with backlight
Face-board	3 keypad
Hook	Stainless steel shackle and Alloy steel hook
Shackle	stainless steel shackle
Battery	AA *4 battery or Lithium Rechargeable battery
Enclosure	Aluminum die-casting case
Accuracy class	equivalent to OIML III
Tare range	100% F.S.
Zero range	4% F.S.
Safe overload	120% F.S.
Overload alarm	100% F.S.+9e
Battery life	more than 100h
Temprange	-10 ~40